

## SAFETY NOTICE

Issued by Angus Pinkerton - Chairman of the Flying & Safety Committee - 29 November 1994

All Hang Glider pilots (including Safety officers, Coaches and Instructors).

If you hold a copy of the BHPA Operations Manual this notice must be inserted into it and retained until it is withdrawn or superseded on instructions from the Chairman FSC.

## **Hang Gliding Harness Failure**

## (Please also refer to Safety Notice FSC.SN.6 issued 06/94)

A fatal accident occurred in Britain earlier this year following a mid-air collision and successful parachute deployment. The pilot's 'pod' - style harness was of the type with only a single rope joining the top of the two should pads, through a ring attached to the rest of the harness, to allow movement in flight. This rope failed, and the pilot fell from his harness to his death.

The BHPA has done a lot of work on ropes and cords since, and the results of the research are available as a full report from the office.

The general conclusion is that, when brand new, "5mm diameter Accessory Cord of Kernmantle Construction" meeting UIAA standards (or the new CEN European standard) is adequate for the likely loads in harness shoulder ropes (and is capable of sustaining nearly 8G in this configuration). It should be noted however, that the opening shock of small pulled-down apex parachutes can exceed this (10 - 15G), and if the pilot happened to be in a head down position when the parachute opened ........

Very importantly we estimate that for ropes used in this way, wear rates may be as much as 10% of strength per 25 hours use (this estimate is based on the testing of 'used' ropes submitted by pilots).

All pilots with harnesses of this type are therefore advised to inspect ropes carefully and replace them if there are any signs of wear. Wear can be indicated by any of; stiffening, a change in cross section, polishing, or a generally 'woolly' appearance. Ropes should be replaced in any case (being careful to get properly approved 'Accessory Cord' as described above) every 50 flying hours.

Changing from 5mm to 6mm rope provides a useful 10% - 25% increase in effective strength. However, going larger than this is likely to create fixing problems due to the larger diameter, and not give much strength improvement since the load is still being applied by the narrow (4mm) ring. Running the rope through a 6mm or 8mm steel Maillon Rapide instead of the ring will provide some further strength increase (but the amount is difficult to quantify).

Continued	

It is very important to make sure that knots are of the correct type, and secure. Tapes are only as strong as the knots securing them! If you have any doubt whatsoever about your knot tying knowledge or skill, get help.

A better answer, if the harness manufacturer is still in business, is to get them to change the design to eliminate the single point failure inherent in the 'sliding-rope-through-a-ring' shoulder support. This should be retained as the primary support, but with sewn in tapes as a backup, for example.

Please exercise great caution if you are tempted to make any DIY harness modifications.