

DHV safety advice: Paraglider harnesses Niviuk Arrow, Niviuk Arrow P

Certification numbers (as far as traceable): PH_317.2020, PH_407.2023

Problem

Some reserve parachutes are not sufficiently fixed in the very spacious harness container. These can move, twist with the connection line or open. This can make it difficult or impossible to deploy the reserve parachute.

Check and safety instructions

Users of the named harnesses are requested to open the harness container and check the position of the reserve parachute container. If the reserve parachute container is inadequately secured and can change its position in the harness container (rotate, tilt, swing back and forth), there is a safety problem. The harness should not be used in this configuration. Instead, users should contact the manufacturer for a technical solution (<https://niviuk.com/de>).

Safety note from the manufacturer

Niviuk is requested to publish a safety message including a solution for repair/rework in a timely manner.

Photos and video documenting the problem [here](#)

Gmund, 10.3.2025

DHV-Referat Sicherheit und Technik

Karl Slezak

